

Continental Automotive Systems, Inc. 21440 W. Lake Cook Rd., Deer Park, IL, 60010, U.S.A. Tel: +1(224)451-0155

Date: March 24, 2022

Product Equality Declaration

We, **Continental Automotive Systems, Inc.**, as the manufacture, hereby declare that we are only and fully responsible for this second source of our product **FE5NA0020**, brand name: **Continental**, model name: **FE5NA0020**. All the hardware of module are all the same, It's just opening up different versions of software for different customers.

The detail differences from the original source are as listed below:

The detail differences from the original source are as fisted below.		
	Original	Second Source
Brand Name	Continental	Continental
Model Name	FE5NA0020	FE5NA0020
HW Version	P4.1	P4.1
SW Version	MODEMSA515M_01.15.62	MODEMSA515M_03.18.00
LTE UL CA	CA-5B,CA-66C	CA-5B,CA-66C, CA-B7C,CA-66B,CA-41C
LTE B71+NR	N.A	DC_71A_n2A,DC_71A_n66A,DC_71A_n78A
EN-DC CLASS 2	N.A	B2A+N77A,B7A+N77A,B13A+N77A,7A,B66A+ N77A,B5A+N77A
Path antenna change	B2A+N77A / Ant1+Ant1 B13A+N77A / Ant1+Ant1 B66A+N77A / Ant1+Ant1 B5A+N77A / Ant1+Ant1	B2A+N77A / Ant1+ Ant2 B13A+N77A / Ant1+ Ant2 B66A+N77A / Ant1+ Ant2 B5A+N77A / Ant1+ Ant2

Except for the above-mentioned modification, all the other portions remain unchanged.

Sincerely,

Certification Manager / Jianming Zhang

Continental Automotive Systems, Inc.

Tel.: +1 224 451 0155

E-mail: jianming.2.zhang@continental.com