
Class II change


The modification of TPM-167, Data applies to: TC-400 (changed From TPM167, FCC ID: LJL041201T), The detail description of modification as belows:

1. New edition sensor the different is the position of pressure hole.





Bottom View



Pressure hole

2. New edition sensor circuit diagram is same as original one, only one different is power supplied from 3V.