

Responses to Non-Conformities (Ref # E00-000496-1; FCC ID: LLP9030)

---

Item 1: Please provide a brief description of the circuit functions of the device along with a statement describing how the device operates.

10/27 – Operational Block Diagram was provided.

Item 2: It appears two copies of the report were provided in one pdf file. Please explain and update if needed.

10/27 – One copy of report was provided.

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.

Responses to Non-Conformities (Ref # E00-000496-1; FCC ID: LLP9030)

---

Item 1: The FCC ID number needs to be placed on its own line or enclosed within a box. Please resubmit a new label.

10/27 - Response: Customer Label Justification

The reason why the labels are in the battery compartment is that the size of the headset label is too large to place on the outside of the unit and in order to have consistent design with the headset label, we decided to place the base label also in the battery compartment. Another reason is for better outlook if the label is in the battery compartment (just like with most of cellular phones).

10/27 – New label was also provided.

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.