

---


**INTERTEK TESTING SERVICE**

Report No.: HK12110333-1QFD

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**



---



**INTERTEK TESTING SERVICE**

Report No.: HK12110333-1QFD

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**


**(Internal)**



**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**



---


**INTERTEK TESTING SERVICE**

Report No.: HK12110333-10JFD

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**



---



**INTERTEK TESTING SERVICE**

Report No.: HK12110333-1QFD

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**



---



**INTERTEK TESTING SERVICE**

Report No.: HK12110333-1(R1)

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**



---

**INTERTEK TESTING SERVICE**

Report No.: HK12110333-1(R1)

**Equipment Photographs**

**Model: XW-BTS1-K & XW-BTS1-W**

**(Internal)**

