


TRANSIENT FREQUENCY BEHAVIOR
12.5 kHz Channel Spacing, No Modulation

Transmitter was being turned "ON"



TRANSIENT FREQUENCY BEHAVIOR
12.5 kHz Channel Spacing, No Modulation
Transmitter was being turned "OFF"

