




Report No.: 9907582

Tested By: Hong, Report No.: 9907582

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement:	X QP	Transducer No.	Start	Stop	Name
		3	9k	30M	ET078
Meas Time:	1 s				
Subranges:	16				
Acc Margin:	20dB				



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9907582

Tested By: Hong, Report No.: 9907582

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.53500	24.6	48.0
0.59000	21.9	48.0

* limit exceeded

Ctrl. No.: N/A