## **INTERTEK TESTING SERVICES**

Report No. : HK11071415-1


Stop 27.28 MHz

Sample No. : 1/4



1 PK VIEW

Start 26.96 MHz



32 kHz/