

SIEMENS

Siemens AG, PD PA CI R&D IWC, Oestliche Rheinbrueckenstr. 50,
76187 Karlsruhe

Telecommunication Certification Body
UL VS Ltd
Offices 18-26
Grove House
Lutyens Close
Chineham Court
Basingstoke
Hampshire
RG24 8AG
United Kingdom

Name	Dr. Christoph Munch
Department	PD PA CI R&D IWC
Telephone	+49 (721) 595-2469
Fax	+49 (721) 595-2326
Mobile	+49 (172) 6521203
E-mail	christoph.muench@siemens.com
Our reference	CM
Date	February 2, 2016

Subject: Firmware modification for compliance with DFS, new rules, see FCC KDB 905462 D02

FCC ID: LYHELN1V1

The firmware (wireless driver) of the Siemens devices with FCC ID: LYHELN1V1 has been enhanced in order to comply with DFS, new rules, see FCC KDB 905462 D02, which requires detection of additional radio patterns. The changes made between the original and updated Firmware for this device are detailed in the operational description submitted as part of this FCC C2PC application.

As a result of the changes detailed above, the following test cases have been tested to verify compliance of the modified FCC ID: LYHELN1V1:

Test cases acc. to. FCC KDB 905462 D02 UNII DFS Compliance Procedures New Rules v01r02, May 15, 2015, Details see test report.

Yours sincerely,



Christoph Muench
System Manager
Siemens AG, PD PA CI BA

Siemens AG
Process Industries and Drives Division; Management: Juergen Brandes
Process Automation; Management: Eckard Eberle

Oestliche Rheinbrueckenstr. 50 Tel.: +49 (721) 595 0
76187 Karlsruhe
Germany

Siemens Aktiengesellschaft: Chairman of the Supervisory Board: Gerhard Cromme;
Managing Board: Joe Kaeser, Chairman, President and Chief Executive Officer; Roland Busch, Lisa Davis, Klaus Helmrich,
Janina Kugel, Siegfried Russwurm, Ralf P. Thomas
Registered offices: Berlin and Munich, Germany; Commercial registries: Berlin Charlottenburg, HRB 12300, Munich, HRB 6684
WEEE-Reg.-No. DE 23691322