SIEMENS

Siemens AG, PD PA CI R&D IWC, Oestliche Rheinbrueckenstr, 50, 76187 Karlsruhe

Telecommunication Certification Body

UL VS Ltd Offices 18-26 **Grove House** Lutyens Close Chineham Court Basingstoke Hampshire

RG24 8AG United Kingdom

Dr. Christoph Mnch Name PD PA CI R&D IWC Department

+49 (721) 595-2469 Telephone +49 (721) 595-2326 Fax +49 (172) 6521203 Mobile

christoph.muench@siemens.com E-mail

Our reference Date

CM February 2, 2016

Subject: Firmware modification for compliance with DFS, new rules, see FCC KDB 905462 D02

FCC ID: LYHMPCIE1V1

The firmware (wireless driver) of the Siemens devices with FCC ID: LYHMPCIE1V1 has been enhanced in order to comply with DFS, new rules, see FCC KDB 905462 D02, which requires detection of additional radio patterns. The changes made between the original and updated Firmware for this device are detailed in the operational description submitted as part of this FCC C2PC application.

As a result of the changes detailed above, the following test cases have been tested to verify compliance of the modified FCC ID: LYHMPCIE1V1:

Test cases acc. to. FCC KDB 905462 D02 UNII DFS Compliance Procedures New Rules v01r02, May 15, 2015, Details see test report.

Yours sincerely,

Christoph Muench System Manager

Che Lack

Siemens AG, PD PA CI BA

Process Industries and Drives Division; Management: Juergen Brandes Process Automation; Management: Eckard Eberle

Oestliche Rheinbrueckenstr. 50 76187 Karlsruhe Germany

Tel.: +49 (721) 595 0