

Siemens AG, PD PA CI R&D IWC, Oestliche Rheinbrueckenstr, 50, 76187 Karlsruhe Telecommunication Certification Body UL VS Ltd Offices 18-26 Grove House Lutyens Close Chineham Court Basingstoke Hampshire RG24 8AG Name Department Dr. Christoph Mnch PD PA CI R&D IWC

Telephone Fax Mobile E-mail +49 (721) 595-2469 +49 (721) 595-2326 +49 (172) 6521203 christoph.muench@siemens.com

Our reference Date CM February 2, 2016

Subject: Firmware modification for compliance with DFS, new rules, see FCC KDB 905462 D02

FCC ID: LYHMSN1V1

United Kingdom

The firmware (wireless driver) of the Siemens devices with FCC ID: LYHMSN1V1 has been enhanced in order to comply with DFS, new rules, see FCC KDB 905462 D02, which requires detection of additional radio patterns. The changes made between the original and updated Firmware for this device are detailed in the operational description submitted as part of this FCC C2PC application.

As a result of the changes detailed above, the following test cases have been tested to verify compliance of the modified FCC ID: LYHMSN1V1:

Test cases acc. to. FCC KDB 905462 D02 UNII DFS Compliance Procedures New Rules v01r02, May 15, 2015, Details see test report.

Yours sincerely,

a. A. d

Christoph Muench System Manager Siemens AG, PD PA CI BA

Siemens AG Process Industries and Drives Division; Management: Juergen Brandes Process Automation; Management: Eckard Eberle Oestliche Rheinbrueckenstr. 50 76187 Karlsruhe Germany

Tel.: +49 (721) 595 0

Siemens Aktiengesellschaft: Chairman of the Supervisory Board: Gerhard Cromme; Managing Board: Joe Kaeser, Chairman, President and Chief Executive Officer; Roland Busch, Lisa Davis, Klaus Helmrich, Janina Kugel, Siegfried Russwurm, Ralf P. Thomas Registered offices: Berlin and Munich, Germany; Commercial registries: Berlin Charlottenburg, HRB 12300, Munich, HRB 6684 WEEE-Reg.-No. DE 23691322