


## FCC ID: M4Y-0XA622H Issued on Sep. 30, 2005

Report No.: FR591307

## 5.5.5. Photographs of Conducted Emission Test Configuration



FRONT VIEW



**REAR VIEW** 

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 21 of 40


Issued Date : Sep. 30, 2005



## FCC ID: M4Y-0XA622H Issued on Sep. 30, 2005

Report No.: FR591307

## 5.6.11. Photographs of Radiated Emission Test Configuration



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 32 of 40

Issued Date : Sep. 30, 2005



FCC ID: M4Y-0XA622H Issued on Sep. 30, 2005

Report No.: FR591307



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 33 of 40

Issued Date : Sep. 30, 2005