

Registration number: W6M21606-15933-C-1

FCC ID: M5X-TA80

IC: 2978A-TA80

**Internal Photos**





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80



Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80








Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80






Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80







Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80







Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80







Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80





# Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M21606-15933-C-1  
FCC ID: M5X-TA80  
IC: 2978A-TA80

