## Advantech Co. Ltd.



No.1, Alley 20, Lane 26, Rueiguang Road, Neihu District, Taipei 114, Taiwan, R.O.C.

## **DTS-UNII Device Declaration Letter**

We have	n it may concern : declared below featured for F CC ID : M82-AIM8Q	CC equipment authorization,			
(1)	DFS Device ☐ Master ,☐ Client with Radar detection capability, ☐ Client without radar detection capability, ☐ N/A				
(2)	Active / Passive Scanning , adhoc mode access point capability				
( )	Frequency Band (MHz)	Active Scanning (the device can transmit a probe (beacon))	passive scanning (where the device is can listen only with no	Ad Hoc Mode or WIFI Direct capability	Access point capability
	2412-2462	☐ Yes , ☒ No	probes) ⊠ Yes ,	☐ Yes , ⊠ No	☐ Yes , ⊠ No
	2422-2452	☐ Yes , ☒ No	∑ Yes , ☐ No	Yes , No	☐ Yes , ⊠ No
	5180-5240	☐ Yes , ☒ No	🛛 Yes , 🔲 No	☐ Yes , 🔀 No	☐ Yes , 🔀 No
	5190-5230	☐ Yes , ☐ No	∑ Yes , ☐ No	☐ Yes , ☐ No	☐ Yes , ☒ No
	5260-5320	Yes , No	Yes , No	Yes , No	Yes , No
	5270-5310 5500-5700	☐ Yes , ☒ No ☐ Yes , ☒ No	⊠ Yes , □ No ⊠ Yes , □ No	☐ Yes , ☒ No ☐ Yes , ☒ No	☐ Yes , ☒ No ☐ Yes , ☒ No
	5510-5670	Yes, No	Yes, No	Yes, No	Yes, No
	5745-5825	Yes, No	Yes, No	Yes, No	Yes, No
	5245-5825	☐ Yes , ☒ No	⊠ Yes , ☐ No	Yes , No	☐ Yes , ☒ No
	5755-5795	☐ Yes , ☒ No	🛛 Yes , 🗌 No	☐ Yes , ☒ No	☐ Yes , 🏻 No
this mode	Meet 15.202 requirement - c below: ster device is defined as a device it is able to select a channel nt device is defined as a device mode is not able to initiate a negative service.	ice operating in a mode in whi and initiate a network by send e operating in a mode in whic	ling enabling signals to other	devices	
devices v	For client devices that have in others) in different bands (which configure the modes of ware and / or hardware is imple y, \bigsim \text{No Apply}, (If apply, p	operations through software, to emented to ensure that proper	nt classes or those that opera he application must provide s operations modes can not be	ate on non-DFS frequen oftware and operations e modified by end user o	cies) or modular description on how or an installer.
(6)	Please help to provide justification how device was restricted to operate in 5600-5650MHz in below.				
	The device operation is di	iscontinued in the absence of	informaion that complies the	requirement.	
Name /	Title : Lily Huang / Assistar	nt Manager Corporate Oua	lity / Certification		
	886-2-2792-7818#1412		.,,		
	6-2-2794-7334				
	اله:-۱۱y.Huang@advantech.com	n.tw			
	: No.1, Alley 20, Lane 26, R	٨	rict, Taipei 114, Taiwan, R.	O.C.	
Signat	cure :	12/2			