

Functional Description

Tune-up procedure

During manufacturing each phone is individually calibrated. Measurement is performed in a fully calibrated setup using an CMU 200 base station simulator (system tester). Measurement procedure is outlined below:

Measurement Procedure:

1. Set the phone to operational voltage and on a predefined band class and channel.
2. The maximum output power is measured when the power control bit is set as all UP bits.
3. Output power is adjusted individually for no higher than maximum compliance power shown in the relevant test reports.

The user has no possibility to change these settings.

