

Mike Kuo

Hi Mike,

Question #1: RF section of internal photos are not clear. Please retake photos to show all the component values.

Ans #1: The clear internal photos are attached. Please refer to it.

Best regards,
Ting

----- Àà§eª ting/ccsemc ©ó 2004/04/27 10:10 AM -----

Mike Kuo <MKUO@CCSEMC.com>

!-¥óªHjG "CCS-Taiwan, Ting (E-mail)" <ting@ccsemc.com.tw>, "CCS-Taiwan, Wklo (E-mail)" <wklo@ccsemc.com.tw>

°Æ¥»§Û°e¡G "Lai, Harris (E-mail)" <harris@ccsemc.com.tw>, Scott Wang <SWang@CCSEMC.com>

2004/04/27 08:57 AM

¥D!@¡G FW: Procomp Informatics Ltd. , FCC ID:MAA-PW8610IM, AN04T3848

-----Original Message-----

From: CERTADM

Sent: Monday, April 26, 2004 5:57 PM

To: Mike Kuo

Subject: Procomp Informatics Ltd. , FCC ID:MAA-PW8610IM, AN04T3848

Notice_content

Question #1: RF section of internal photos are not clear. Please retake photos to show all the component values.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

--

4/27/2004