FCC ID: MAD-BR5811B

Description of Permissive Change

This report is prepared for FCC class II permissive change. The difference compared with the Report No.:RF930507H06 design is as the following

u Add one external antenna for model : BR5811bE as below:

Original Report (Report No.:RF930507H06)				
For 5GHz				
No.	Model No.	Gain (dBi)	Antenna Type	Antenna Connector
1	ANT05535	17.0dBi	Directional, Patch Panel (Internal Antenna)	Probe Pin
2	R0420-058	8.0dBi	Dipole, Omni (External Antenna)	N (Plug)
3	MTI09009	23.0dBi	Directional, Patch Panel (External	N (Jack)
	(4C10021)		Antenna)	
u	Add one new antenna			
For 5GHz(5250~5850MHz):				
'No.	Model No.	Gain (dBi)	Antenna Type	Antenna Connector
Α	1GP-51809	9.0dBi	Dipole, Omni (External Antenna)	N female(Plug)
u Add 5470~5725MHz (new band)				
'No.	Model No.	Gain (dBi)	Antenna Type	Antenna Connector
1	ANT05535	17.0dBi	Directional, Patch Panel (Internal Antenna)	Probe Pin

Report No. RF930507H06F | Reference No.: 951115H02