
## Appendix C. Setup Photographs

## **Conducted Emission**



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C1 of C3
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01

Report No.: FR812802B





SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C2 of C3
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01






## **Radiation Emission**

FRONT VIEW

REAR VIEW



FAX: 886-2-2696-2255