
Appendix C. Setup Photographs

Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C1 of C4
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01

Report No.: FR812802A





SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C2 of C4
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01




Radiation Emission

Mode 1-6



FRONT VIEW



REAR VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C3 of C4
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01






Mode 7

FRONT VIEW





REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C4 of C4
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01