



5/16/06

American TCB
6731 Whittier Blvd.
McLean, VA 22101

Re: FCC ID: MBPPAT1322-0300

In response to your Comment Letter dated 5/5/06:


1. Uploading Agent Authorization Letter today.
2. SCM will only be using the FCC ID: MBPPAT1322-0300. The other label is obsolete.
3. Please see page 3 of the revised Test Report.
4. Please see page 12 of the revised Test Report.
5. Please see [ages 31-32 of revised Test Report.
6. Please see page 45 of the revised Test Report.
7. Please see page 31 of the revised Test Report.
8. The second harmonic was more than 20 dB below the limit, in the ground floor noise, so was not reported.
9. Uploading revised User's Manual today.

Please don't hesitate to contact me if you have any questions regarding this application.

Best Regards

A handwritten signature in black ink, appearing to read "R. Cole".

Bob Cole
President
EMCE Engineering



EMCE Engineering
44366 S. Grimmer Blvd Fremont, CA 94538
510-490-4307 / 510-490-3441 Fax