



**Digi International**  
**11001 Bren Road East**  
**Minnetonka, MN 55343**  
**952-912-3444 tel**  
**952-912-4991 central fax**

The ConnectCore Wi-9P 9215 module complies with FCC 15.407(c) and IC RSS-210 A.9 by implementing the following:

a) *Discontinuance of transmission in the absence of information:*

The device firmware prevents any frame transmission if corresponding frames are not received for transmission; and

b) *Discontinuance of transmission upon operational failure:*

The device firmware re-boots operation if a failure is detected, and no frames are transmitted until proper operation is discerned.

21/02/2009

A handwritten signature in black ink, appearing to read "Meyer".

Sébastien Meyer  
Lead Hardware Engineer  
Phone: +49-7667-908-134, Fax: +49-7667-908-200  
[mailto:sebastien\\_meyer@digi.com](mailto:sebastien_meyer@digi.com)

--  
Digi International GmbH Branch Breisach  
Kueferstr. 8, 79206 Breisach, Germany  
Tax: 315/5781/0242 / VAT: DE153662976 / Reg. Amtsgericht Dortmund HRB 13962  
Directors: Subramanian Krishnan, Dieter Vesper  
<http://www.digi.com>