

## Mike

---

**From:** Mike [mike@celectronics.com]  
**Sent:** Tuesday, December 06, 2005 11:12 AM  
**To:** Kyle Fujimoto (Kyle Fujimoto)  
**Subject:** FCC ID: MG33010

Mr. Fujimoto:

In order for processing of this application (FCC ID: MG33010) to continue, the following issue(s) will have to be addressed:

- 1) In the test report, there appears to be antennas that are out of calibration given the test dates mentioned in the report. In addition, the dates of the test setup photos do not match the test dates in the test report. Please clarify and explain.
- 2) The test report mentions that modifications were made, but no modification letter was provided. Please provide a modification letter stating that the modifications mentioned in the report will be done in production.
- 3) The operational description is insufficient with the requirements FCC rules. Part 2 Section 1033 states that a brief description of the circuit functions of the device along with a statement describing how the device operates must be submitted with the application. Please submit an operational description sufficient for this rule part.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is MG33010-1.

Best Regards,

Mike Christensen  
Evaluator  
Compatible Electronics TCB  
Phone: 714-579-0500  
Fax: 714-579-1850  
[www.celectronics.com](http://www.celectronics.com)