



URC-3010BA0 IR/RF Remote Control

The following modifications were found to be necessary for compliance and will be included in production.

List of modifications:

1. C32 was 12 pF, now 8.2 pF
2. C35 was 6.8 pF, now 12 pF
3. C37 was not populated, now 0.5pF

If you have any questions or need additional information, please contact the undersigned at (714) 820-1094.

Regards,

Jesse Mendez

Jesse Mendez

Electrical Engineer