

CAUTION

Do not expose the cable connector to any substance that may be corrosive. Exposure to materials such as harsh detergents, disinfectants, or animal urine may damage connector parts. Cap the end of the connector when disconnected from the receiver. Cable connector caps are available from DSI. Please contact your DSI representative for more information.

DSI[™]

119 14th Street NW, Suite 100
St. Paul, MN 55112 U.S.A.
(651)481-7400 Fax(651)481-7404

TRX-1, F1

CATALOG#



272-9000-001

DEVICE ID:



123457

MANUFACTURED 05/07/2012

SERIAL# 123457

Assembled in U.S.A.

These devices comply with Part 15 of the FCC rules and Industry Canada (IC) RSS 210. Operation is subject to the following conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may cause undesired operation.

FCC ID: MHATRUTRX
IC: 5681A-MHATRUTRX