

May 9, 2012

Equipment Authorization Branch
Laboratory Division
Office of Engineering and Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Gentlemen:

During the course of filing the system application, an FCC ID for the external device was changed from MHATRXDSI to MHATRUTRX. Since the filing is for a system consisting of an implanted and associated external transceiver, the manual has been changed to delete any reference to the incorrect FCC ID. A replacement manual is being filed. The filed agent authorization letter is also being updated. Due to the small physical size of the external transceiver, the compliance statement has been placed in the system users manual. The corrected sheets are intended to replace the statement in the filing.

Sincerely yours,

A handwritten signature in cursive script that reads "Phillip Inglis" followed by a small capital letter "P".

Phillip Inglis

TRP Inc.