

TELEPHONE: (352) 472-5500 (888) 472-2424 FAX: (352) 472-2030 E-MAIL: <u>info@timcoengr.com</u> WEBSITE: www.timcoengr.com

6/11/99

Mr. Joe Dichoso FCC 7435 Oakland Mills Road Columbia, Md. 21045

SUBJECT: ADI FCCID: MKDAR447

REFERENCE: EA94026

The unit was tested with a tuned dipole antenna connected to the unit. I tested the unit scanning and in the single frequency mode. In the single frequency mode I tuned the dipole to the frequency that the UUT was tuned to. In the scanning mode I adjusted the antenna at the center of the band that I was scanning.

The unit was tested with and antenna connected, NOT a termination load.

The UUT cannot tune to any other frequencies than the 430-470MHz and could not easily be modified. Do you need some kind of statement from the manufacturer?

I have asked the manufacturer to clarify the frequency range, I tested the range that the sample would and assumed that was the correct range. When the report was typed I guess that the range from the manual was picked up. I will clarify this up as soon as I hear from the maker.

BEST REGARDS,

Sid Sanders

F:\CUS\A\ADI\jd906110.doc

TIMCO ENGINEERING, INC. • 25355 WEST NEWBERRY ROAD • P.O. BOX 370 • NEWBERRY, FL 32669