

20 April, 2006

RE: FCC ID: MLBHLIK-1T

Attention: Mr. Timothy R. Johnson

Dear Mr. Timothy Johnson,

Please find the following our reply to your comment;

1. Please find page 8 and 12 of the revised test report. The report has been modified owing to the following reason;

As the level of emission level was very low, for spurious emission, the test has been performed by using average detector under 15.209, which is stricter limit than 15.231.

Thank you very much for your prompt attention.

Best regards,

Kanako Sanda

Kanako Sanda (Ms.)
Head Office EMC Lab.
EMC Service Dept.

TEL +81-596-24-8116
FAX +81-596-24-8124
E-mail: Kanako.Sanda@jp.ul.com

