

**APPENDIX 3: Photographs of test setup**

**Radiated emission**  
**(Below 1GHz)**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Radiated emission**  
**(Above 1GHz)**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Worst case position**

**Below 1 GHz (Horizontal: X-axis / Vertical: Y-axis)  
Above 1 GHz (Horizontal: X-axis / Vertical: Y-axis)**

**X-axis**



**Y-axis**



**Z-axis**



**Worst case position**



**Mechanical Key (folded out)**



**Mechanical Key (folded in) Worst**

**End of Report**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124