

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1



Photo 2

Worst Case Position

ECU

Below 30 MHz

Y-axis

Above 30 MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124