



## Justification

I, the Manufacturer, hereby declare under our sole responsibility that the RF module WM-G-MR-01 integrated in the following models does not have Bluetooth function and remove all components about it.

|              |  |
|--------------|--|
| Product      | BAR CODE PRINTER   |
| Model        | MB200i-W2, MB201i-W2   |
| Manufacturer | Sato Corporation<br>1-207, Onari-cho, Omiya-ku, Saitama-shi, Saitama, Japan 330-0852 |

Components relevant to Bluetooth function under "Cross(X Marking)" in the parts location diagram "SiP 11g only Component Placement Drawing" are removed from the RF module and those components correspond with ones in the schematics "FD09\_FD10\_BlockDiagram\_Schematics".

Representative Person's Name: Mr. Masayuki Sato

Title: Project Leader

Signature: M. Sato

Date: November 2<sup>nd</sup>, 2006