

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

Worst Case Position

Below 30MHz **Antenna:** **X-axis / ECU: X-axis**
Above 30MHz **Antenna:** **Horizontal: X-axis Vertical: Z-axis**
 ECU: **Horizontal: X-axis Vertical: X-axis**


**Antenna
X-axis**




Y-axis




Z-axis




**ECU
X-axis**



Y-axis



Z-axis



UL Japan, Inc.


Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position



Mechanical Key (Inserted)



Mechanical Key (Not Inserted) Worst

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124