
FCC TEST REPORT Report No.: F371707

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.




FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : MQ4ARM904 Page No. : 1 of 3 Issued Date : Oct. 13, 2003 FCC TEST REPORT Report No.: F371707



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : MQ4ARM904

 TEL: 886-2-2696-2468
 Page No. : 2 of 3

FAX: 886-2-2696-2255 Issued Date: Oct. 13, 2003


FCC TEST REPORT Report No.: F371707

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : MQ4ARM904
Page No. : 3 of 3
Issued Date : Oct. 13, 2003