## To: tjohnson@AmericanTCB.com Subject: Re: Review of AboCom System, Inc., FCC ID: MQ4WBD512

Dear Timothy,

Thanks for your information. We have modified the report as per your review comments and have the file attached for your review. Please see the explanation below:

- 1) We conducted the SAR test per your requirement.

  Please find the SAR report as file attached for your review.
- 2) We modified the user"s manual as per your requirement and have it attached for your reference.
- 3) About 6 dB bandwidth was incorrectly measured: we remeasured and modified it in section 3 in FCC report. Please find the FCC report as file attached for your review.
- 4) About difference between the Reading column in dBm and the output power in dBm column:

we modified it in section 4 (page 12 of 38) of FCC report as file attached for your review.

5) Page 19 of 38 of the test report contains an additional colume "Average Factor:

We have modified it (in page 19 of 38). Please also find the revised FCC report for your review.

6) About quesiotn 6, that's because we add 10dB external attenuator.

I hope the supplementary statisfy all your requirement for reviewing this application.

If you have further question, please feel free to let me know.

Best Regards Sunny Liu