

July 8, 2008

RE: Schrader Electronics Limited

FCC: MRXALM4MA4

The following is in response to the comments made on the above referenced application.

1) The antenna appears to be external to the board. Is this antenna internal to the case or external? Was the antenna present or terminated into appropriate impedance? Test Photos do not appear to show any external connection other than power. Additionally, if the antenna was not present, then test data regarding 15.111 should be provided. Note there is a reference to Table 4.1 – but it doesn't exist.

While it is somewhat hard to distinguish, the antenna is a piece of wire embedded into the plastic housing. The photograph below highlights its location.

