

March 21, 2002

Hansol Electronics Inc.

27-29, Hanchun-ri, Ducksan-myun, Jinchon-kun, Chungbuk, 365-840, Korea

Tel: 82-43-530-8500 Fax: 82-43-536-8105

Hansol Electronics Inc.

FCC ID: MSAB15BF-A

Dear Mr. Mike,

We, Hansol Electronics Inc. have made the following change to the subject device as below;

- 1) R101 and R 103 were removed in main board.
- 2) R102 changed to 100 ohm from 22 ohm in main board.
- 3) C101 changed to 5 pF from 10 pF in main board.

Sincerely,

S. P. Yang / Hansol Electronics Inc.