



Date: 25 JUN 2021 15:11:46

-BE-NR-LOW, SISO-A, 802.11ax20-HE0, Ch169




--BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch169




Date: 25 JUN 2021 15:12:56

-BE-NR-LOW, SISO-A, 802.11ax20-HE0, Ch173




-BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch173




Date: 25 JUN 2021 15:14:04

-BE-NR-LOW, SISO-A, 802.11ax20-HE0, Ch177




-BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch177

Test Report N° 210209-01.TR34




Date: 25.JUN.2021 15:15:13

-BE-NR-LOW, SISO-A, 802.11ax40-HE0, Ch167




-BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch167




Date: 25.JUN.2021 15:16:24

-BE-NR-LOW, SISO-A, 802.11ax40-HE0, Ch175




-BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch175




Date: 25.JUN.2021 15:39:48


-BE-NR-LOW, SISO-A, 802.11ax80.HE0, Ch171




-BE-NR-HIGH, SISO-A, 802.11ax80.HE0, Ch171




-BE-NR-LOW, SISO-A, 802.11ax160-HE0, Ch163




-BE-NR-HIGH, SISO-A, 802.11ax160-HE0, Ch163




BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch169




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch169



BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch173



BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch173




Date: 25.JUN.2021 18:03:11

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch177




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch177




Date: 25.JUN.2021 18:07:17

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch169




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch169




Date: 25.JUN.2021 18:08:24

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch173




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch173

Test Report N° 210209-01.TR34




Date: 25.JUN.2021 18:09:30

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch177




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch177




Date: 25.JUN.2021 18:10:35

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch167




BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch167




Date: 28.JUN.2021 09:58:40

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch175



BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch175




Date: 28.JUN.2021 09:33:31

BE-NR-LOW, SISO-B, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, SISO-B, 802.11ac80-VHT0, Ch171




Date: 28.JUN.2021 10:00:35

BE-NR-LOW, SISO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, SISO-B, 802.11ac160-VHT0, Ch163




Date: 25.JUN.2021 18:15:03

BE-NR-LOW, SISO-B, 802.11ax20-HE0, Ch169




BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch169




Date: 25.JUN.2021 18:16:10

BE-NR-LOW, SISO-B, 802.11ax20-HE0, Ch173




BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch173




Date: 25.JUN.2021 18:17:16

BE-NR-LOW, SISO-B, 802.11ax20-HE0, Ch177




BE-NR-HIGH, SISO-B, 802.11ax20-HE0, Ch177




Date: 25.JUN.2021 18:18:22

BE-NR-LOW, SISO-B, 802.11ax40-HE0, Ch167




BE-NR-HIGH, SISO-B, 802.11ax40-HE0, Ch167




Date: 28.JUN.2021 09:38:31

BE-NR-LOW, SISO-B, 802.11ax40-HE0, Ch175




BE-NR-HIGH, SISO-B, 802.11ax40-HE0, Ch175




Date: 28.JUN.2021 10:02:43

BE-NR-LOW, SISO-B, 802.11ax80-HE0, Ch171




BE-NR-HIGH, SISO-B, 802.11ax80-HE0, Ch171




Date: 25.JUN.2021 18:21:42

BE-NR-LOW, SISO-B, 802.11ax160-HE0, Ch163




BE-NR-HIGH, SISO-B, 802.11ax160-HE0, Ch163

Test Report N° 210209-01.TR34




Date: 25.JUN.2021 18:11:02

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch169




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch169




Date: 25.JUN.2021 18:38:05

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch173




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch173




Date: 25.JUN.2021 18:41:34

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 25 JUN 2021 16:42:40

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch167




BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch167




Date: 25 JUN 2021 17:29:05

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch175




BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175




Date: 25 JUN 2021 17:30:34

BE-NR-LOW, MIMO-A, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171

Test Report N° 210209-01.TR34




Date: 25 JUN 2021 17:35:24

BE-NR-LOW, MIMO-A, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-A, 802.11ac160-VHT0, Ch163




Date: 25 JUN 2021 17:14:36

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch169




BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch169




Date: 25 JUN 2021 17:15:43

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch173



BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch173

Test Report N° 210209-01.TR34




Date: 25 JUN 2021 17:18:50

BE-NR-LOW, MIMO-A, 802.11ax20-HE0, Ch177




BE-NR-HIGH, MIMO-A, 802.11ax20-HE0, Ch177




Date: 25 JUN 2021 17:17:55

BE-NR-LOW, MIMO-A, 802.11ax40-HE0, Ch167




BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch167




Date: 25 JUN 2021 17:40:03

BE-NR-LOW, MIMO-A, 802.11ax40-HE0, Ch175




BE-NR-HIGH, MIMO-A, 802.11ax40-HE0, Ch175




Date: 25 JUN 2021 17:42:55

BE-NR-LOW, MIMO-A, 802.11ax80-HE0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ax80-HE0, Ch171




Date: 25 JUN 2021 17:45:51

BE-NR-LOW, MIMO-A, 802.11ax160-HE0, Ch163




BE-NR-HIGH, MIMO-A, 802.11ax160-HE0, Ch163




Date: 25 JUN 2021 19:57:16

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch169




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch169

Test Report N° 210209-01.TR34




Date: 25.JUN.2021 19:58:22

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch173




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch173




Date: 25.JUN.2021 19:59:28

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177




Date: 25.JUN.2021 20:00:36

BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch167




BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch167




Date: 28.JUN.2021 08:47:04
BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch175




BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




Date: 28.JUN.2021 08:54:28
BE-NR-LOW, MIMO-B, 802.11ac80-VHT0, Ch171



BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171




Date: 28.JUN.2021 08:03:39
BE-NR-LOW, MIMO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-B, 802.11ac160-VHT0, Ch163

Test Report N° 210209-01.TR34




Date: 25 JUN 2021 20:05:03

BE-NR-LOW, MIMO-B, 802.11ax20-HE0, Ch169




BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch169




Date: 25 JUN 2021 20:03:09

BE-NR-LOW, MIMO-B, 802.11ax20-HE0, Ch173




BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch173




Date: 25 JUN 2021 20:07:15

BE-NR-LOW, MIMO-B, 802.11ax20-HE0, Ch177




BE-NR-HIGH, MIMO-B, 802.11ax20-HE0, Ch177




Date: 28.JUN.2021 09:05:55

BE-NR-LOW, MIMO-B, 802.11ax40-HE0, Ch167




BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch167




Date: 28.JUN.2021 09:10:12

BE-NR-LOW, MIMO-B, 802.11ax40-HE0, Ch175




BE-NR-HIGH, MIMO-B, 802.11ax40-HE0, Ch175




Date: 28.JUN.2021 09:11:55

BE-NR-LOW, MIMO-B, 802.11ax80-HE0, Ch171




BE-NR-HIGH, MIMO-B, 802.11ax80-HE0, Ch171

Test Report N° 210209-01.TR34



Date: 28.JUN.2021 09:25:50
 BE-NR-LOW, MIMO-B, 802.11ax160-HE0, Ch163



BE-NR-HIGH, MIMO-B, 802.11ax160-HE0, Ch163