


Appendix C. Photographs of Setup

Spurious Radiation



FRONT VIEW

REAR VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 FCC ID : MSQP527