

Training Research Co., Ltd.

 255 Nanyang Street, Shiji; Taipei Hsien 221, Taiwan, ROC.

 TEL:886-2-26935155
 FAX:886-2-26934440

 Email: report@txclab.com.tw

March 3, 2003

RE	:	ASUSTeK Computer
FCC ID	:	MSQWL140

Dear Timothy:

After the review of your comments, we have made some response upon your advice; they are summarized as follows:

- 1. The label is updated per your request, please find them in the uploads.
- 2. The RF Exposure statements is inserted into the manual as shown in the uploads.
- 3. The pages of the report you have specified is updated and uploaded.
- 4. The RBW of our measurement is followed the FCC instruction, please find the material we have uploaded and comment if any other issue should us be noted.
- 5. The manual is inserted with the compliance sheet separately and please find the materials as the uploads.

Should you have any questions or more information is requested, please don't hesitate to ask us. Thank you.

Sincerely yours, Eric Wong Project Engineer Training Research Co Ltd.