

SX4P Internal Photos

Project Number: 3039424
November 9, 2003

Internal Photos of the
Phonecell SX4P

FCC ID: MTF030865

For

Telular, Inc.

Test Performed by:
Intertek ETL Semko
1950 Evergreen Blvd, Suite 100
Duluth, GA 30096

Test Authorized by:
Telular, Inc.
580 Old Willets Path
Hauppauge, NY 11788

List of Figures

Figure 1-1: Internal photograph, SX4P enclosure with internal components.....	3
Figure 1-2: Internal photograph, SX4P enclosure (bottom)	4
Figure 1-3: Internal photograph, SX4P enclosure (top).....	5
Figure 1-4: Internal photograph, RF PCB (top).....	6

Figure 1-5: Internal photograph, RF PCB (bottom).....	7
Figure 1-6: Internal photograph, speaker (back).....	8
Figure 1-7: Internal photograph, Speaker (top)	9
Figure 1-8: Internal photograph, Keypad PCB (top) .	Error! Bookmark not defined.
Figure 1-9: Internal photograph, Keypad PCB (bottom)	Error! Bookmark not defined.
Figure 1-10: Internal photograph, LCD PCB (top)....	Error! Bookmark not defined.
Figure 1-11: Internal photograph, LCD PCB (bottom)	Error! Bookmark not defined.
Figure 1-12: Internal photograph, Handset (top and bottom)t.	Error! Bookmark not defined.




Figure 1-1: Internal photograph, SX4P enclosure with internal components




Figure 1-2: Internal photograph, SX4P enclosure (bottom)



Figure 1-3: Internal photograph, SX4P enclosure (top)




Figure 1-4: Internal photograph, RF PCB (top)




Figure 1-5: Internal photograph, RF PCB (bottom)



Figure 1-6: Internal photograph, speaker (back)



Figure 1-7: Internal photograph, Speaker (top)

