
SX6P GSM 850/1900 Deskphone – Top Removed




SX6P GSM 850/1900 Deskphone – RF Board Component Side ITM3208 00400030604000 227 03-08-04 CD3

 $SX6P\ GSM\ 850/1900\ Deskphone-RF\ Board\ Solder\ Side$ 000 GHP

SX6P GSM 850/1900 Deskphone – Daughter Card Component Side, Shield Installed



 $SX6P\ GSM\ 850/1900\ Deskphone-Daughter\ Card\ Component\ Side,\ Shield\ Removed$ 



 $SX6P\ GSM\ 850/1900\ Deskphone-Daughter\ Card\ Solder\ Side$ 

