

Chris Harvey

From: aven.zhou [aven.zhou@cn.ccsemc.com]
Sent: Monday, May 26, 2008 3:59 AM
To: charvey-tcb@ccsemc.com
Cc: charvey-tcb@ccsemc.com; lucy.tsai@ccsemc.com; tillying@gmail.com
Subject: Re:Uni-Art Precise Products Ltd, FCC ID: MVASP2890-001R, Assessment NO.: AN08T7897, Notice#1
Attachments: User Manual_0520.pdf; Internal Photo_0520.pdf; schematic diagram of LF912U-001.pdf; Label Location_0520.pdf; SZ080402B02-EF_0526.pdf; technical specification sheets of LF912U-001-0 SPEC.pdf

Dear Charvey,

Please kindly find the reply below [in blue](#).

If there is any question, please contact me without hesitation!

Thanks & Best regards!

Aven.zhou (Miss) / □ □ □

Compliance Certification Service(Shenzhen) Inc.

Tel: 0755-28055000 ext. 601

E-mail: aven.zhou@cn.ccsemc.com

tillying@gmail.com

MSN : tilly_ping@hotmail.com

Skype: aven_zzp

<charvey-tcb@ccsemc.com>

□□□□ <aven.zhou@cn.ccsemc.com>, <tillying@gmail.com>

2008-05-14 20:49

□□□□□ <charvey-tcb@ccsemc.com>, <lucy.tsai@ccsemc.com>

□□□ Uni-Art Precise Products Ltd, FCC ID: MVASP2890-001R, Assessment NO.: AN08T7897, Notice#1

Dear Aven Zhou,

You are listed as the Technical Contact for the above referenced TCB application. The following item(s) need (s) to be resolved before the review can be continued:

1. FCC Section 15.101 lists several types of Receiver devices and the type of approval required for each. Please provide a better description of this receiver's operation and indicate which type of receiver this is according to the list in FCC 15.101. Please note that only certain types of receivers can be Certified for FCC Compliance. The Receiver application was filed with Equipment Class PCR, which is not a valid class code.

Please provide the correct equipment class for this receiver device.

<Aven> The equipment class is CYY.

2. The Users Manual indicates that the Carrier Frequency is 900MHz (on page P2), but the test report indicates 912-913MHz. Please correct the Users Manual to indicate the correct carrier frequencies of this device.

<Aven> The attached is the revised user manual.

5/28/2008

3. The Receiver photos show an RF Module with the RF Shield covering the circuit. Please submit photographs with the RF shield removed to show the circuit under the RF Shield.

<Aven> The attached is revised photo.

4. Please provide the technical specification sheets and the schematic diagram for the UHF Module in the Receiver device. Please provide a more detailed description of the Auto Scan tuning feature of the receiver.

<Aven> The attached is the schematic diagram for the UHF RF Module

5. FCC 15.19 requires that the label wording be placed on the device unless the device is too small. The receiver device seems sufficiently large to place the wording of 15.19 on the device. Also, please note that the wording as listed in the manual should match the wording of 15.19 (this device complies with Pt. 15 of the FCC Rules..)

<Aven> The attached is the revised label.

6. Please explain how the Receivers operation during the emissions test complies with the Operating Conditions of ANSI C63.4:2003 Section 12.1.

<Aven> The attached is the revised report.

7. There are no emissions listed in the test report above 1000MHz. Please update the test report to indicate the highest frequency measured for this 913MHz receiver device.

<Aven> The attached is the revised report(p15&20).

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Chris Harvey
Charvey-tcb@ccsemc.com