

天祥公證行有限公司 Intertek Testing Services Hong Kong Ltd. 香港九龍青山道五七六號製衣中心二字樓 2/F., Garment Centre, 576 Castle Peak Road Kowloon, Hong Kong.

Telephone (852) 2173 8888 Facsimile (852) 2786 1903 www.intertek.com

То	:	Federal Communication Commission (FCC&TCB)			
Attn.	:	Reviewing Engineer	Date	:	December 29, 2010

RE. : Report Revision Notification

Intertek Testing Services FCC Report No. HK10080316-1 dated October 25, 2010.

Please be informed that all the content recorded in the above captioned report will be voided. These captioned report are now superseded by revised Intertek Testing Services report number HK10080316-1(R1) dated December 29, 2010.

In Report No. HK10080316-1(R1), the following has been changed:

Pages Description

8 & 13 Revise handset battery from "700mAh" to "550mAh".Superseded report only revises the wrong rating to the correct rating (tested rating).The test result and others unchanged.

Thank you for your attention.

11

Nip Ming Fung, Melvin Supervisor