




Report no.: HK10090439-1  
Ringing Mode  
AC Mains



Date: 5.OCT.2010 01:55:32

Ctrl No.: N/A