



Intertek Testing Services

ETL SEMKO

Report No.: 0011593

Tested By Ben, Report No.:0011593


Scan Settings (1 Range)

Frequencies Receiver Settings
Start Stop Step IF BW Detector M-Time Atter Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement: x GP

Meas Time: 7 s
Subranges 16
Acc Margin 20dB

Transducer No. Start Stop Name
21 9k 30M EVC698



PAGE 1

30 MHz

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0011593

Tested By: Ben, Report No.: 0011593

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	GpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results