



Intertek Testing Services

ETL SEMKO

Report No.: 9906319

Mode: Charging


Tested By: Hong, Report No.: 9906319

Scan Settings (1 Range)

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450K	30M	5k	10K	PK	20ms	AMTO	LN OFF	60dB

Final Measurement: 0 QP	Transducer No.	Start	Stop	Name
Meas Time: 1 s	3	9k	30M	EI078
Subranges: 16				
Acc Margin: 20dB				

dBuV Mkr : 30.00000MHz 9.7 dBuV



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906319

Mode: Charging

Tested By: Hong, Report No.: 9906319

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO


Report No.: 9906319

Mode: Standby

Tested By: Hong, Report No.: 9906319
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	10ms	AUTO	LN OFF	60dB

Final Measurement: X QP	Transducer No.	Start	Stop	Name
Meas Time: 1 s	3	9k	30M	EI078
Subranges: 16				
Acc Margin: 20dB				



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906319

Mode: Standby

Tested By: Hong, Report No.: 9906319

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Report No.: 9906319

Mode: Transmission

Tested By: Hong, Report No.: 9906319


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: N QP

Transducer No. Start Stop Name
3 9k 30M EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906319

Mode: Transmission

Tested By: Hong, Report No.: 9906319

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A