MODIFICATIONS TO THE DEVICE FIG. 5.14



New capacitor C1 shown in side view.

Issued: 9/18/98 Page 29 of 51

MODIFICATIONS TO THE DEVICE FIG. 5.15



New capacitor C1 installed in Model JLC7-18, top view.

MODIFICATIONS TO THE DEVICE FIG. 5.16



New capacitor C1 installed in Model JLS, top view.

MODIFICATIONS TO THE DEVICE FIG. 5.17

