

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position
Antenna (Horizontal: X0-axis/ Vertical: Y0-axis)


**Antenna
X0-axis**




**Antenna
X90-axis**




Y0-axis




Y90-axis



Z0-axis




Z90-axis




Worst Case Position
Antenna (Horizontal: X-axis/ Vertical: Y-axis)


Antenna
X-axis



Y-axis




Z-axis




Worst Case Position
Module (Horizontal: X-axis/ Vertical: X-axis)

Module
X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN
Telephone : +81 596 24 8999
Facsimile : +81 596 24 8124