

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

Below 1 GHz



Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission

Above 1 GHz




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical:Y-axis)

Above 1 GHz (Horizontal: Y-axis/ Vertical:Y-axis)

960MHz (Horizontal: Z-axis/ Vertical:Y-axis)

Module

X-axis



Y-axis



Z-axis



Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical:X-axis)

Above 1 GHz (Horizontal: Y-axis/ Vertical:Z-axis)

960MHz (Horizontal: Z-axis/ Vertical:X-axis)

Antenna

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124