

2/28/08

To the Director of Certification,

Axcess International Inc. respectfully requests the following Class II permissive change on

Model: Dot™ Credential Tag FCC: Identifier: N6E-433DOT07

The firmware has been modified to add beaconing capability to our Dot credential tag already certified. Beaconing will occur no faster than once every ten seconds when this mode has been enabled on the tag. No hardware modifications or changes have been made to this device.

Thank you for your attention.

Sincerely,

Raj Bridgelall VP Engineering

Axcess International Inc.