

Chris Harvey

From: September Radecki [september.radecki@ccsemc.com]
Sent: Wednesday, February 21, 2007 12:17 PM
To: Chris Harvey
Cc: Sunny Shih; Michael Heckrotte; Chi Tsou; Christine Vu; Thu Chan
Subject: RE: Sierra Wireless Inc., FCC ID: N7N-MC5725U, Assessment NO.: AN07T6524 & AN07T6523, Notice#1

Attachments: Authorization letter N7N-MC5725U.pdf; Confidentiality Request N7N-MC5725U (Short and Long).pdf; 06U10743-6 FCC IC SAR REPORT.pdf; 2130751 Sprint AirCard 595U User Guide - rev2.0.pdf



Authorization letter N7N-MC5725U.pdf; Confidentiality Request N7N-MC5725U (Short and Long).pdf; 06U10743-6 FCC IC SAR REPORT.pdf; 2130751 Sprint AirCard 595U User Guide - rev2.0.pdf

Hi Chris,

Here are the answers to your questions regarding the above-referenced project.

1. It appears as though some of the exhibits submitted for this application may actually belong to other devices. The FCC ID listed on the application Form 731 and label is N7N-MC5725U, where the FCC ID listed in the Users Manual is N7N-AC595U. The Confidentiality and Short-Term Confidentiality letters shows FCC ID: N7N-MC5725 (without the 'U', which represents an already approved device). Please verify that the Users Manual submitted in this application is the correct manual for this device and replace as necessary.

<Answer> New updated and revised User's Manual is attached.

2. The External Photographs submitted show a USB computer connected host device, but the application seem to imply that the EUT is a MC5725 module with a 52 pin edge connector. Please clarify which part of the device is the EUT.

<Answer> The external photos are correct. The EUT is a USB device; it is a Wireless USB CDMA modem module.

3. The confidentiality letters indicates a request to have the Declaration of Similarity letter held confidential; however there is no such exhibit. This problem may be related to the issue of the FCC ID number above (it may be the wrong letter).

<Answer> Please see new short and long term confidentiality letter, attached.

4. The letter of authorization in the Pt. 15 application is the correct CCS format but is more than 1 year old. The letter of Authorization in the Pt.22/24 application is less than 1 year old, but is no in the correct CCS format. Please provide a CCS format letter of authorization dated within a year of the filing of this application.

<Answer> Please see new Authorization Letter, attached.

5. According to the NVLAP web site, the NVLAP accreditation 200065-0 is for the facility located at 561F Monterey Rd, Morgan Hill. According to the test report the testing was performed in the new facility located at 47173

Benicia St., Fremont. Please indicate if this new facility is covered under the same accreditation or a separate accreditation.

<Answer> The new facility is covered under the same accreditation according to the Engineering Manager, Michael Heckrotte.

6. The SAR test report table of contents indicates that section 8 of the test report is a tabulation of the SAR test results; however, section 8 is missing from the SAR test report. Please submit an updated SAR test report to include the tabulated SAR test data.

<Answer> The SAR Report is complete, but was submitted in 2 parts, because of the client's confidentiality request. The pages with photos have been extracted from the original

Report and removed. Attached is the complete report, without the pages extracted. The attachments remain as originally submitted. Please note that the client has requested short term and long term confidentiality on this project.

Thanks for your help and patience. Also, Chris, there is also an IC-CB application (AN07I1959) for this EUT. Sierra is wanting these grants as soon as possible.

Kindest regards,
September

-----Original Message-----

From: Thu Chan
Sent: Tuesday, February 20, 2007 12:38 PM
To: September Radecki
Cc: Sunny Shih; Michael Heckrotte; Chi Tsou; Christine Vu; Thu Chan
Subject: FW: Sierra Wireless Inc., FCC ID: N7N-MC5725U, Assessment NO.: AN07T6524 & AN07T6523, Notice#1

Hi September,

Please sort out and assign the response person for the questions below need to be addressed.

Thanks,
Thu

Thu Chan
Compliance Certification Services
47173 Benicia Street,
Fremont, CA 94538
Main: 510-771-1000
Direct: 510-771-1122
Fax: 510-661-0888
Email: thu.chan@ccsemc.com

-----Original Message-----

From: Chris Harvey [mailto:charveyemc@verizon.net]
Sent: Monday, February 19, 2007 9:23 AM
To: Thu Chan
Subject: FW: Sierra Wireless Inc., FCC ID: N7N-MC5725U, Assessment NO.: AN07T6524 & AN07T6523, Notice#1

Thu, this also relates to AN07T6523 - Pt. 15 application (I forgot to indicate that in the subject heading of the first e-mail).

Thanks,

Chris

-----Original Message-----

From: charvey-tcb@ccsemc.com [mailto:charvey-tcb@ccsemc.com]
Sent: Monday, February 19, 2007 12:19 PM
To: Thu.Chan@CCSEMC.COM
Cc: charvey-tcb@ccsemc.com
Subject: Sierra Wireless Inc., FCC ID: N7N-MC5725U, Assessment NO.: AN07T6524, Notice#1

Dear Thu,

I have performed the initial review of the above referenced TCB applications. The following items need to be addressed before the review can be completed:

1. It appears as though some of the exhibits submitted for this application may actually belong to other devices. The FCC ID listed on the application Form 731 and label is N7N-MC5725U, where the FCC ID listed in the Users Manual is N7N-AC595U. The Confidentiality and Short-Term Confidentiality letters shows FCC ID: N7N-MC5725 (without the 'U', which represents an already approved device). Please verify that the Users Manual submitted in this application is the correct manual for this device and replace as necessary.

2. The External Photographs submitted show a USB computer connected host device, but the application seem to imply that the EUT is a MC5725 module with a 52 pin edge connector. Please clarify which part of the device is the EUT.

3. The confidentiality letters indicates a request to have the Declaration of Similarity letter held confidential; however there is no such exhibit. This problem may be related to the issue of the FCC ID number above (it may be the wrong letter).

4. The letter of authorization in the Pt. 15 application is the correct CCS format but is more than 1 year old. The letter of Authorization in the Pt.22/24 application is less than 1 year old, but is no in the correct CCS format. Please provide a CCS format letter of authorization dated within a year of the filing of this application.

5. According to the NVLAP web site, the NVLAP accreditation 200065-0 is for the facility located at 561F Monterey Rd, Morgan Hill. According to the test report the testing was performed in the new facility located at 47173 Benicia St., Fremont. Please indicate if this new facility is covered under the same accreditation or a separate accreditation.

6. The SAR test report table of contents indicates that section 8 of the test report is a tabulation of the SAR test results; however, section 8 is missing from the SAR test report. Please submit an updated SAR test report to include the tabulated SAR test data.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Chris Harvey
charvey-tcb@ccsemc.com