

Photos of Radiation Measuring Setup

Adapter 1

30MHz to 1GHz



x-axis



y-axis



z-axis



Adapter 2
30MHz to 1GHz



x-axis



y-axis



z-axis



Adapter 3
30MHz to 1GHz



x-axis



y-axis



z-axis



Adapter 4
30MHz to 1GHz



x-axis



y-axis



z-axis



Battery
30MHz to 1GHz



x-axis




y-axis



z-axis



Adapter 1
above 1GHz




x-axis




y-axis



z-axis



Adapter 2
above 1GHz



x-axis




y-axis



z-axis



Adapter 3
above 1GHz



x-axis



y-axis



z-axis




Adapter 4
above 1GHz



x-axis




y-axis



z-axis



Battery
above 1GHz



x-axis



y-axis



z-axis



Photos of Conduction Measuring Setup Cable



USB

